

PVC FLOORING INSTALLATION

FLOORING WELDING METHOD

Seamless splice welding method

Advantage


No need welding rods or cold-welding fluid

Disadvantage

Difficult to install, installer should have rich experience

Installation

- Put a onto b (2cm overlap part c)
- Cut the overlap part c
- Stick b in close proximity to a



Cold-welding method (base on seamless splice)

Advantage


Cold-welding fluid is a kind of diaphanous liquid, the joint gap will be unobvious.

Disadvantage

Expansive and difficult to install

Installation

- Stick a paper tape on the seams between each flooring pieces
- Cut the paper tape along the seams
- Infuse cold-welding fluid through the seams
- Peel the paper tape after 20mins (according to cold welding fluid instructions)



Hot welding method (base on seamless splice)

Advantage

Cheap and almost all vinyl flooring can use hot welding install method.

Disadvantage

Difficult to install

Installation

- Make groove by using groove machine (2/3 of the flooring thickness)
- Clean the dust inside groove
- Put the welding rod into the groove with welding gun (500-600 degree centigrade)
- Cut the redundant part over flooring with quarter-moon knife

