

FAQ

HOW TO DEAL WITH FLOORING HOLLOWING AND EDGE WARPING

Reason analysis

- High moisture content of subfloor
- There is crack in subfloor
- No damp-proof course
- Primer is not incomplete sealed
- Use water-based adhesive on non-absorbent subfloor
- Adhesive is not dry
- High dimension stability performance of flooring
- Self-leveling is too soft
- Adhesion ability of adhesive is not good
- Haven't press the flooring after adhesive installation

Measures to avoid

Analysis the type of subfloor and fix the unqualified area under standard construction, chose suitable accessories

Solution

- Repair with high-strength putty
- Remove and re-install self-leveling (if hollowing happened)
- Polish (if no hollowing happened)

