

FAQ

HOW TO DEAL WITH SELF-LEVELING HEIGHT DIFFERENCE

Reason analysis

- Subfloor is too soft and sanding
- Primer is not incomplete sealed
- Self-leveling dehydrate too fast
- Product own problem

Measures to avoid

Coat more primer, and refuse expired products

Solution

- Repair with high-strength putty
- Pre-install another self-leveling layer

