

FAQ

HOW TO DEAL WITH UNEVEN COLOR SELF-LEVELING

Reason analysis

- Uniform water mixing rate
- Self-leveling is not totally dry
- Substrate absorbency difference in subfloor

Measures to avoid

Reasonable treatment of subfloor and install self-leveling under standard construction

Solution

- Re-install another self-leveling layer
- Wait for self-leveling to dry

